

BUILDING SAFETY CERTIFICATE


The school building of Stanford World school at village Garh Sukker P.O Sukker in Tehsil Dharmshala Distt. Kangra H.P. was inspected by the concerned Junior Engineer. As per the report of Junior Engineer the buildings has neither been designed nor been constructed by this office. No earthquake resistant norms have been adopted for this building. No structural drawing approved by the competent Govt. agency have been produced. The structure is Non-Engineered Structure. Hence the structural safety of this building cannot be ensured specifically from earthquake point of view. This department will not be responsible for any type of loss of life and property etc. if this structure fails under any circumstances. However as per visual inspection the building has been found to be safe at present only. This certificate is valid for academic session for 2023-24.



Junior Engineer
HP.PWD Sub Division .II
Dharmshala



Assistant Engineer,
HPPWD Sub Division. II
Dharmshala.



Executive Engineer
Dharmshala Division
HPPWD Dharmshala

Place: Dharamshala

Dated:

HIMACHAL PRADESH
PUBLIC WORKS DEPARTMENT

N0.PW/DD/CB/WAB/B-17/2023

16748-49

Dated:- 13.3.2023

Copy forwarded to the Director, Stanford World School Vill. Garh Sukker, Tehsil Dharamshala, Distt. Kangra (HP) for information with reference to his application dated 1-3-2023 please.

Copy forwarded to the Assistant Engineer, Dharamshala Sub-Division No.II, HPPWD, Dharamshala for information with reference to his office letter No.2011dated 09-03-2023.



Executive Engineer,
Dharamshala Division,
HPPWD, Dharamshala


Principal
Stanford World School


Secretary
Stanford World School
Dharamshala