

BUILDING SAFETY CERTIFICATE

No.

Dated: 5-4-2024


Certified that the existing building Stanford World School (name of the building or premises) at Vill Gash Sukker P.O Sukker, Dharamshala (address) comprised of Dharamshala basement(s) and Ground floor & First floor (upper floors) owned/occupied by Stanford World School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of H.P.P.W.D. (Name of Department/ Govt.) on 2/04/2024 (date of inspection) in the presence of Vivek Thakur (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto classes Nursery to 9th (X/ XII) with effect from..... for a period of 2024-25 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 5-4-2024 at 6-4-2025 by

* Strike out whichever is not applicable.


J. E. Anand


Assistant Engineer
Dharamshala, Sub Divn. No. II
HP PWD, Dharamshala
Name: _____

Designation : _____

Name & Address of Department/ Office: _____


(Assistant Engineer & above officer of concerned Govt. Department only)


Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only


* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

SAFETY CERTIFICATE

The school building of Stanford World School at village Garh Sukker Post Office Sukker Tehsil Dharmshala Distt. Kangra H.P. was inspected by the concerned Junior Engineer. As per the report of Junior Engineer this building has neither been designed nor been constructed by this office. No earthquake resistant norms have been adopted for this building. No structural drawings approved by the competent Govt. agency have been produced. The structure is a Non-Engineered Structure. Hence the structural safety of this building cannot be ensured specifically from earthquake point of view. This department will not be responsible for any type of loss of life and property etc. if this structure fails under any circumstances. However as per visual inspection the building has been found to be safe at present only. This certificate is valid for academic session for 2024-25 .


Junior Engineer
HP.PWD Sub Division .II
Dharmshala .


Assistant Engineer,
HPPWD Sub Division. II
Dharmshala.


Executive Engineer
Dharmshala Division
HPPWD Dharmshala

Place: Dharamshala

Dated:

HIMACHAL PRADESH
PUBLIC WORKS DEPARTMENT

N0.PW/DD/CB/WAB/B-17/2024


63-64

Dated:-

5-4-2024

✓ Copy forwarded to the Director, Stanford World School Vill. Garh Sukker, Tehsil Dharamshala, Distt. Kangra (HP) for information with reference to his application dated 03-02-2024 please.

Copy forwarded to the Assistant Engineer, Dharamshala Sub-Division No.II, HPPWD, Dharamshala for information with reference to his office letter No.15 dated 03-04-2024.


Executive Engineer,
Dharamshala Division,
HPPWD, Dharamshala